

Inspection Photos
Operator: Simcoe
API: 067-06767
Date: 3/2/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing largely with smooth brome, western wheatgrass, and crested wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward. Kochia weeds are mowed.



Photo 4. View of reference area comprised of irrigated grass field with grasses such as smooth brome and western wheatgrass observed.