

Inspection Photos
Operator: Simcoe
API: 067-09336
Date: 3/2/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing largely with intermediate wheatgrass, crested wheatgrass, and western wheatgrass.



Photo 3. View of kochia debris, up to 4-ft tall observed on the well pad and in the southern project area (inset).



Photo 4. View of reference area comprised of open grass field with smooth brome, crested wheatgrass, and western wheatgrass observed.