

Inspection Photos
Operator: Simcoe
API: 067-07419
Date: 3/2/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with grasses in a dormant/grazed vegetative condition. Livestock present at this time.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of open grass field. Vegetation is in a grazed/dormant vegetative condition at this time. Livestock present.