

Inspection Photos
Operator: Simcoe
API: 067-09270
Date: 3/2/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with grasses in a dormant/grazed vegetative condition.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area (beyond fence) comprised of open grass field. Vegetation is in a grazed/dormant vegetative condition at this time.