

Inspection Photos
Operator: Simcoe
API: 067-06981
Date: 3/2/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area (beyond fence) comprised of open grass field. Vegetation is comprised of smooth brome, western wheatgrass, and crested wheatgrass.