

Inspection Photos  
Operator: Simcoe  
API: 067-07039  
Date: 3/2/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Working area is fenced. Revegetation is progressing with grasses such as western wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area (beyond fence) comprised of open grass field. Vegetation is comprised of smooth brome, western wheatgrass, and crested wheatgrass.