

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402976667

Date Received:

03/08/2022

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

481662

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u>	Operator No: <u>10633</u>	Phone Numbers
Address: <u>1801 CALIFORNIA STREET #2500</u>		Phone: <u>(303) 774-4017</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>(720) 925-1820</u>
Contact Person: <u>Schuyler Hamilton</u>		Email: <u>shamilton@civiresources.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402962908

Initial Report Date: 02/22/2022 Date of Discovery: 02/22/2022 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR SESE SEC 17 TWP 2N RNG 67W MERIDIAN 6

Latitude: 40.133591 Longitude: -104.905887

Municipality (if within municipal boundaries): Firestone County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 440933
 Spill/Release Point Name: Bighorn 17H-P267 Well API No. (Only if the reference facility is well) 05- -
 No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>0</u>	Estimated Condensate Spill Volume(bbl): <u>0</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>>=5 and <100</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: Approximately 88 barrels of produced water

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): _____
 Weather Condition: 5F and cloudy
 Surface Owner: FEE Other(Specify): Private Landowner

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A compromised above ground storage tank resulted in the release of approximately 88 barrels of produced water within lined secondary containment. The release was completely contained within the lined secondary containment. A hydro-vacuum was initially utilized to remove approximately 75 barrels of the released produced water. Additional remediation efforts will occur during warmer weather to recover all released fluid. The storage tank has been drained and removed from service for repairs and investigation into root cause of the failure. Photographic evidence will be provided demonstrating the removal of the released fluids and the condition of the liner following remediation efforts.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
2/23/2022	Landowner		-	Email
2/22/2022	City of Firestone		-	Email
2/22/2022	Weld County		-	OEM Online Reporting

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
Waters of the State: _____ Public Water System: _____
Residence or Occupied Structure: _____ Livestock: _____
Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
Enter the approximate time of discovery _____ (HH:MM)
Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
Enter the Document Number of the Initial Accident Report, Form 22 _____
Was there damage during excavation? _____
Was CO 811 notified prior to excavation? _____

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
Estimated Volume of Impacted Solids (cu. yd.): _____

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property. <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>03/08/2022</u>		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>0</u>	<u>0</u>	<input type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	<u>88</u>	<u>88</u>	<input type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>YES</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
The release was completely contained within and recovered from the synthetic liner on the pad surface. No soil or other media was impacted; therefore, there are no impact extents. Photographic evidence is provided demonstrating the removal of impacted containment fill and the condition of the liner following remediation efforts.			
Soil/Geology Description:			
Pea gravel within lined secondary containment.			
Depth to Groundwater (feet BGS) <u>10</u>		Number Water Wells within 1/2 mile radius: <u>7</u>	
If less than 1 mile, distance in feet to nearest		Water Well <u>400</u> None <input type="checkbox"/>	Surface Water <u>3285</u> None <input type="checkbox"/>
		Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>600</u> None <input type="checkbox"/>
Additional Spill Details Not Provided Above:			

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 03/07/2022

Root Cause of Spill/Release Equipment Failure

Other (specify)

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Above ground produced water storage tank

Describe Incident & Root Cause (include specific equipment and point of failure)

A compromised above ground storage tank resulted in the release of approximately 88 barrels of produced water within lined secondary containment. The release was completely contained in lined secondary containment. A hydro-vacuum was initially utilized to remove approximately 75 barrels of the released produced water. The secondary containment area has cobblestone as a stabilizing material above the liner. The cobblestone was pressure washed to remove the remaining impacts. The decontamination rinse water was then removed from the containment area with a hydro-vacuum.

Describe measures taken to prevent the problem(s) from reoccurring:

The storage tank was drained and removed from service for repairs. Investigation into root cause of the failure determined corrosion on the tank bottom resulted in the release. The storage tank will be replaced with an epoxy lined tank. Photographic evidence has been provided demonstrating the decontaminated cobblestone stabilizing material and the condition of the synthetic liner following remediation efforts.

Volume of Soil Excavated (cubic yards):

Disposition of Excavated Soil (attach documentation) [] Offsite Disposal [] Onsite Treatment [] Other (specify)

Volume of Impacted Ground Water Removed (bbls):

Volume of Impacted Surface Water Removed (bbls):

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure: [X] Corrective Actions Completed (documentation attached, check all that apply)
[] Horizontal and Vertical extents of impacts have been delineated.
[] Documentation of compliance with Table 915-1 is attached.
[X] All E&P Waste has been properly treated or disposed.
[] Work proceeding under an approved Form 27 (Rule 912.c).
Form 27 Remediation Project No:
[] SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

This Form 19 Supplemental is being submitted to request closure for the Spill/Release ID (481662). The spill was completely contained within lined secondary containment. All potentially impacted cobblestone within the liner was pressure washed and the remaining produced water was removed via hydro-vacuum. The liner was inspected for any leaks or damage and none was found. A photolog showing the current condition of the lined secondary containment is provided.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Print Name: Maggie Graham

Title: Senior Project Manager Date: 03/08/2022 Email: Maggie.Graham@apexcos.com

Table with 2 columns: COA Type, Description

Attachment List

Att Doc Num

Name

402977403

PHOTO DOCUMENTATION

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)