

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31NESE

Location ID: 324073




Photo #6077 from entrance to location.



Photo #6078 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31NESE

Location ID: 324073



Photo #5835 from inspection #699804093 conducted on 2/1/22.



Photo #6079 Insufficient tracking BMP at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /31NESE

Location ID: 324073




Photo #5836 from inspection #699804093 conducted on 2/1/22.