

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402977773

Date Received:
03/09/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 952 ECHO LANE SUITE 480

City: HOUSTON State: TX Zip: 77024

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rikki Ross

405-921-1825

rikki@d90energy.com

David Boyer

303-994-0000

david@d90energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690900193

Inspection Date: 02/10/2022

FIR Submit Date: 02/11/2022

FIR Status: _____

Inspected Operator Information:

Company Name: D90 ENERGY LLC

Company Number: 10706

Address: 952 ECHO LANE SUITE 480

City: HOUSTON State: TX Zip: 77024

LOCATION - Location ID: 449274

Location Name: Rabbit Ears 0681 Number: 23 County: _____

Qtrqtr: SWNE Sec: 23 Twp: 6N Range: 81W Meridian: 6

Latitude: 40.476982 Longitude: -106.454006

FACILITY - API Number: 05-057-00 Facility ID: 449274

Facility Name: Rabbit Ears 0681 Number: 23

Qtrqtr: SWNE Sec: 23 Twp: 6N Range: 81W Meridian: 6

Latitude: 40.476982 Longitude: -106.454006

CORRECTIVE ACTIONS:

1 CA# 159652

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 03/11/2022

Response: CA COMPLETED

Date of Completion: 02/14/2022

Operator Comment: The northern load out valve was replaced on 2/14/2022. Snow has been removed and staining from containment and on dike wall was cleaned immediately.

COGCC Decision: _____

--

Date: 3/9/2022 9:10:18 AM

--	--