

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402034481
Receive Date:
05/07/2019

Report taken by:
CHRIS CANFIELD

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation. Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Phone: <u>(970) 336-3500</u>
	Zip: <u>80217-3779</u>	Mobile: <u>(970) 515-1698</u>
Contact Person: <u>Gregory Hamilton</u>	Email: <u>Gregory.Hamilton@anadarko.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION
Remediation Project #: 13047 Initial Form 27 Document #: 401970454

PURPOSE INFORMATION

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other _____

SITE INFORMATION N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>LOCATION</u>	Facility ID: <u>327359</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>BALLANTYNE USX WW-61N66W 1NENE</u>	Latitude: <u>40.084085</u>	Longitude: <u>-104.720208</u>	
	** correct Lat/Long if needed: Latitude: <u>40.084443</u>	Longitude: <u>-104.720378</u>	
QtrQtr: <u>NENE</u>	Sec: <u>1</u>	Twp: <u>1N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Non-crop land
Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? No
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Buildings are located approximately 620 feet northeast and a livestock pen is located approximately 490 feet north of the former produced water vessel location.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	SOILS	No impacts encountered	Soil sampling and laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Two (2) partially buried produced water vessels (PWVs) were removed from the Wakefield 41-4 location on January 14, 2019. Groundwater and impacted soil were not encountered in the PWV excavation. A liner was not present beneath the PWVs at this site. The PWVs at this facility have been permanently removed. Soil samples from the excavation were submitted for laboratory analysis, to determine if a release occurred. The general site layout, soil sample location, and PWV excavation dimensions are depicted on the Sample Location Map provided as Figure 1.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On January 14, 2019, following removal of the 2 PWVs, soil samples were collected from the sidewalls and base of the excavation. The soil samples were field-screened for volatile organic compounds using a photoionization detector (PID). Soil samples B01@5' and B02@5' were submitted for laboratory analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX), total petroleum hydrocarbons (TPH) – gasoline range organics (GRO) by EPA Method 8260C, TPH diesel and oil range organics (DRO and ORO) by EPA Method 8015, pH, and electrical conductivity (EC). Laboratory analytical results for soil samples B01@5' and B02@5' indicate that BTEX, TPH, pH, and EC concentrations and levels were in full compliance with COGCC Table 910-1 allowable levels. The soil sample analytical results are summarized in Table 1, and the laboratory analytical report is attached.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

No groundwater was encountered in the excavation.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 2
Number of soil samples exceeding 910-1 0
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 0

NA / ND

ND Highest concentration of TPH (mg/kg) _____
NA Highest concentration of SAR _____
BTEX > 910-1 No
Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 910-1 _____

_____ Highest concentration of Benzene (µg/l) _____
_____ Highest concentration of Toluene (µg/l) _____
_____ Highest concentration of Ethylbenzene (µg/l) _____
_____ Highest concentration of Xylene (µg/l) _____
_____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
_____ Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Laboratory results indicate that soil samples B01@5' and B02@5' were in full compliance with COGCC Table 910-1 allowable levels, therefore, no soils were removed. The excavation area was backfilled and contoured to match pre-existing site conditions.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory results indicate that soil sample concentrations were in compliance with COGCC allowable levels. Groundwater was not encountered in the PVV excavation. Based on the analytical data presented herein, assessment is complete at this site and no further activities are required. Upon COGCC approval of the Initial Form 27, Kerr-McGee will submit a Supplemental Form 27 request for a No Further Action (NFA) determination for this site.

Soil Remediation Summary

In Situ

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

Ex Situ

- _____ Excavate and offsite disposal
- _____ If Yes: Estimated Volume (Cubic Yards) _____
- _____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
- _____ Excavate and onsite remediation
- _____ Land Treatment
- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Other _____

Groundwater Remediation Summary

- _____ Bioremediation (or enhanced bioremediation)
- _____ Chemical oxidation
- _____ Air sparge / Soil vapor extraction
- _____ Natural Attenuation
- _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other Final Report _____

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Produced Water Vessel Closure _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes _____

Do all soils meet Table 910-1 standards? Yes _____

Does the previous reply indicate consideration of background concentrations? No _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? No _____

Is additional groundwater monitoring to be conducted? No _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site will be reclaimed in accordance with COGCC 1000 Series Reclamation Rules.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/14/2019

Date of commencement of Site Investigation. 01/14/2019

Date of completion of Site Investigation. 01/14/2019

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Based on the analytical data provided herein, Kerr-McGee is requesting an NFA determination for this location.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Gregory Hamilton

Title: Senior Staff Env Rep

Submit Date: 05/07/2019

Email: Gregory.Hamilton@anadarko.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: CHRIS CANFIELD

Date: 05/14/2019

Remediation Project Number: 13047

Condition of Approval**COA Type****Description**

COA Type	Description
0 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

Att Doc Num	Name
402034481	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
402034495	SITE MAP
402034496	ANALYTICAL RESULTS
402034499	ANALYTICAL RESULTS
402042650	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

User Group	Comment	Comment Date
Environmental	The Colorado Oil & Gas Conservation Commission (COGCC) has reviewed and hereby approves your request for a determination of No Further Action at the above-referenced location. However, should future conditions indicate that contaminant concentrations in soils exceed COGCC standards, or if ground water is found to be impacted, further investigation and/or remediation activities may be required.	05/13/2019

Total: 1 comment(s)