

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401779550

Date Received:

10/09/2018

Spill report taken by:

CHESSON, BOB

Spill/Release Point ID:

455231

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers
Address: <u>1001 NOBLE ENERGY WAY</u>		Phone: <u>(970) 3045329</u>
City: <u>HOUSTON</u>	State: <u>TX</u>	Zip: <u>77070</u>
Contact Person: <u>Jacob Evans</u>		Mobile: <u>()</u>
		Email: <u>jacob.evans@nblenergy.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401654823

Initial Report Date: 05/27/2018 Date of Discovery: 05/26/2018 Spill Type: Historical Release

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NESE SEC 26 TWP 4N RNG 65W MERIDIAN 6

Latitude: 40.281430 Longitude: -104.621410

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY ☐ Facility/Location ID No _____

Spill/Release Point Name: Beebe Draw RG 26-9, 23 ☒ No Existing Facility or Location ID No.

Number: _____ ☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: CROP LAND Other(Specify): _____

Weather Condition: Sunny 80

Surface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☒ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During dismantlement of the tank battery a historical release was discovered. Excavation of impacted material will be scheduled.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
5/26/2018	Bob Chesson	COGCC	-	
5/26/2018	Roy Rudisill	Weld County	-	
5/26/2018	Troy Swain	Weld County	-	
5/27/2018	Noble Land	Landowner	-	

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

CORRECTIVE ACTIONS

#1	Supplemental Report Date: 10/01/2018
Cause of Spill (Check all that apply) <input type="checkbox"/> Human Error <input type="checkbox"/> Equipment Failure <input checked="" type="checkbox"/> Historical-Unknown <input type="checkbox"/> Other (specify) _____	
Describe Incident & Root Cause (include specific equipment and point of failure) Historical impacts were discovered during tank battery dismantlement.	
Describe measures taken to prevent the problem(s) from reoccurring: The tank battery was dismantled and excavation of impacted soil has been completed. Noble Energy conducts AVO inspections of facilities on a routine basis.	
Volume of Soil Excavated (cubic yards): 6312	
Disposition of Excavated Soil (attach documentation) <input checked="" type="checkbox"/> Offsite Disposal <input type="checkbox"/> Onsite Treatment <input type="checkbox"/> Other (specify) _____	
Volume of Impacted Ground Water Removed (bbls): _____	
Volume of Impacted Surface Water Removed (bbls): _____	

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☒ Work proceeding under an approved Form 27

Form 27 Remediation Project No: 11925

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Jacob Evans

Title: Environmental Coordinator Date: 10/09/2018 Email: jacob.evans@nblenergy.com

Condition of Approval

COA Type**Description**

0 COA

Attachment List

Att Doc Num**Name**

401779550	SPILL/RELEASE REPORT(SUPPLEMENTAL)
401794818	FORM 19 SUBMITTED

Total Attach: 2 Files

General Comments

User Group**Comment****Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)