

**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**




**Photo 1 – Tank Battery Sign**



**Photo 2 – Unmarked Riser in NW Corner**



**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 3 – Unmarked Riser in NW Corner**



**Photo 4 – Heater Heaters**

**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 5 – Gathering Lines**



**Photo 6 – Produced Water Tanks**



**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 7 – Produced Water Tanks**



**Photo 8 – Crude Oil Tanks**



**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 9 – Production Equipment**



**Photo 10 – Unmarked Risers North of Treaters**



**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 11 – Unmarked Risers North of Treaters**



**Photo 12 – LACT**



**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 13 – Heater Treaters**



**Photo 14 – Compressor – Drain Pit missing Labels**



**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 15 – LACT**



**Photo 16 – Electrical House**

**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 17 – Unmarked Riser**




**Photo 18 – Flare and ECD**



**Inspection Photos**  
**Location Name: Razor 11 CPB**  
**Location ID: 433611**



**Photo 19 – Unmarked Riser**



**Photo 20 – Unmarked Risers**

