

Inspection Photos
Location Name: HOWARD-66N64W /27SENE
Location #: 323657



Photo #1
Howard 8-27 (05-123-13326) Wellsite
Plugged & Abandoned | PA
Plugging Operations
Perf for squeeze



Photo #2
Howard 8-27 Wellsite
Plugged & Abandoned | PA
Plugging Operations
Site safety signage
prior photo

Inspection Photos
Location Name: HOWARD-66N64W /27SENE
Location #: 323657



Photo #3
Howard 8-27 Wellsite
Plugged & Abandoned | PA
Plugging Operations
Battery sign
prior photo