

Inspection Photos
Location Name: Sargent Farms 2B
Location ID: 318036



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Sargent Farms 2B
Location ID: 318036




Photo 3 TB location SE of wellsite

Photo 4 TB sign

Inspection Photos
Location Name: Sargent Farms 2B
Location ID: 318036



Photo 5 TB tank on the left (east tank) has about 5 ft. of fluid in it, and PW tank is about $\frac{3}{4}$ full.



Photo 6 Horiz. Heated Sep. and Gas Meter Run