

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402047877

Date Received:  
05/17/2019

**FIR RESOLUTION FORM**

Overall Status: FRQ

CA Summary:

1 of 5 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 383 INVERNESS PKWY, STE 360  
City: ENGLEWOOD State: CO Zip: 80112

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Stephen M Strachan</u>	<u>303-790-9115</u>	<u>sms@strachanexploration.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900685  
Inspection Date: 05/15/2019 FIR Submit Date: 05/16/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC Company Number: 83130  
Address: 383 INVERNESS PKWY, STE 360  
City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 324823

Location Name: FRAZEE-619S50W Number: 6SENW County: KIOWA  
Qtrqr: SENW Sec: 6 Twp: 19S Range: 50W Meridian: 6  
Latitude: 38.435220 Longitude: -103.056530

FACILITY - API Number: 05-061-00 Facility ID: 212935

Facility Name: FRAZEE Number: 1-6  
Qtrqr: SENW Sec: 6 Twp: 19S Range: 50W Meridian: 6  
Latitude: 38.435220 Longitude: -103.056530

CORRECTIVE ACTIONS:

**1** CA# 125245

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS Date: 05/20/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: We are in receipt of the inspection effective Thursday evening, 5/16/19, with a compliance date set at Monday, 5/20/19. The soil staining shown in Photo #2, load out facility, is a localized spotting of oily waste; Photo #3, well head, is also a localized spotting of oily waste. We believe this staining should be allowed a 30-day clean up period, which would allow for contractor engagement and sufficient time to do the clean up. As today is Friday, May 17 and the weekend approaching, finding a contractor or contractors and arranging for disposal before end

of work Monday May 20, is an unreasonable request. 30 days will allow for a diligent and prudent approach to clean up.

COGCC Decision: **Not Approved**

COGCC Representative: Per conversations with Environmental staff, the 30 day extension request is denied. Oily waste must be cleaned up by Friday 5/24/2019.

COGCC Supervisor: Per conversations with Environmental staff, the 30 day extension request is denied. Oily waste must be cleaned up by Friday 5/24/2019.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: We are in receipt of the inspection 5/16/19, Thursday evening, with a compliance date set at 5/20/19, Monday. The soil staining shown in Photo #2, load out facility, is a localized spotting of oily waste; Photo #3, well head, is also a localized spotting of oily waste. We believe this staining should be allowed a 30 day clean up period, which would allow for contractor engagement and sufficient time to work the clean up. As today is Friday May 17 and the weekend approaching, finding contractors and arranging for disposal before Monday, an unreasonable request. 30 days will allow for a diligent and prudent approach to clean up.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Stephen M. Strachan

Signed: \_\_\_\_\_

Title: President

Date: 5/17/2019 2:29:25 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402047877	FIR RESOLUTION FORM
402050345	FIR RESOLUTION SUBMITTED

Total Attach: 2 Files