

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400738112

Date Received:

11/22/2014

Spill report taken by:

Spencer, Stan

Spill/Release Point ID:

440118

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>OXY USA WTP LP</u>	Operator No: <u>66571</u>	<b>Phone Numbers</b>
Address: <u>760 HORIZON DR #101</u>		Phone: <u>(970) 2633651</u>
City: <u>GRAND JUNCTION</u> State: <u>CO</u> Zip: <u>81506</u>		Mobile: <u>(970) 6440014</u>
Contact Person: <u>Edward Brotsky</u>		Email: <u>edward_brotsky@oxy.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400738112

Initial Report Date: 11/21/2014 Date of Discovery: 11/19/2014 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NENW SEC 9 TWP 7S RNG 97W MERIDIAN 6

Latitude: 39.466615 Longitude: -108.225749

Municipality (if within municipal boundaries): \_\_\_\_\_ County: GARFIELD

Reference Location:

Facility Type: WELL PAD  Facility/Location ID No 335018

Spill/Release Point Name: \_\_\_\_\_  No Existing Facility or Location ID No.

Number: \_\_\_\_\_  Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Land Use:

Current Land Use: OTHER Other(Specify): Rangeland

Weather Condition: Clear, cold

Surface Owner: OTHER (SPECIFY) Other(Specify): Oxy Private

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State  Residence/Occupied Structure  Livestock  Public Byway  Surface Water Supply Area

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

At approximately 7:00PM Wednesday, (November 19th, 2014) a produced/brine water release occurred when an Oxy contractor was priming frac trucks. One of the hoses was not connected to the pump manifold. When the hoses were opened from the missile to the pumps, approximately 30bbl of produced/brine water was spilled on the ground. Most of the liquid was immediately recovered, but approximately 5bbl was amongst the equipment and unrecoverable.

List Agencies and Other Parties Notified:

### OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
11/20/2014	COGCC	Stan Spencer	970-625-2497	None
11/20/2014	Garfield County	Kirby Wynn	970-625-5905	None

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Edward Brotsky

Title: Environmental Specialist Date: 11/22/2014 Email: edward\_brotsky@oxy.com

### Condition of Approval

#### COA Type

#### Description

COA Type	Description
0 COA	

### Attachment List

Att Doc Num	Name
400738112	SPILL/RELEASE REPORT(INITIAL)
400738221	AERIAL PHOTOGRAPH
400738222	TOPOGRAPHIC MAP
400739293	FORM 19 SUBMITTED

Total Attach: 4 Files

### General Comments

User Group	Comment	Comment Date
Agency	Collect and analyze representative soil samples from spill area following completion and demob of frac crew when pad becomes accessible. Submit Supplemental F-19 with analytical results showing cleanup to Table 910-1 standards or an F-27 to assess and remediate.	11/24/2014

Total: 1 comment(s)