

# Final Reclamation Inspection

March 8, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 322869

Inspection Document #: 697503793

Weld County, CO

NESE Section 34 T5N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FANNY B #2  
Location ID: 322869



**Photo 1.** Photo taken from the well location, facing East. Photo illustrates the well location is not reflective of reference area vegetative levels. Well location is bare and some subsidence was observed. It does not appear the well location has been seeded.





Inspection Photos  
Location Name: FANNY B #2  
Location ID: 322869



**Photo 2.** Photo taken from the well location, facing North. See comments under Photo 1.







**Photo 3.** Photo taken from the associated offsite tank battery, facing Southeast. Photo illustrates the tank battery is still active for another nearby well.