

Inspection Photos

API: 071-08703

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/9/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08703 | Date: 3/9/2022

Inspection Photos



Photo 1. Facing southwest along the main road. Stormwater has caused erosion along the road side. BMP's need to be installed. Lat/Long:37.05530,-104.725025.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08703 | Date: 3/9/2022

Inspection Photos



Photo 2. Facing southwest along the main road. There is a lot of vehicle traffic causing rutting of the road. Maintenance and grading of the road will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08703 | Date: 3/9/2022

Inspection Photos



Photo 3. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08703 | Date: 3/9/2022

Inspection Photos



Photo 4. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08703 | Date: 3/9/2022