

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1NWNE

Location ID: 334716



Photo #6122 from entrance to location.



Photo #6123 Location lacks stabilization.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1NWNE

Location ID: 334716



Photo #5899 from inspection #699804129 conducted on 2/10/22.



Photo #6124 Location lacks stabilization.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1NWNE

Location ID: 334716



Photo #5901 from inspection #699804129 conducted on 2/10/22.



Photo #6125 Insufficient tracking BMP located at entrance to location.