

Interim Reclamation and Stormwater Inspection

March 7, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 420296

Location Name: Circle B Land Tract 5 /21-692

Inspection Document #: 702800013

Garfield County, CO

SWNE Section 21 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Circle B Land Tract 5 /21-692
Facility #: 420296



Photo 1. Photo taken from the northern production area facing southeast shows an overview of the eastern portion of the Location.



Inspection Photos
Location Name: Circle B Land Tract 5 /21-692
Facility #: 420296



Photo 2. Photo taken from the southwestern production area facing south shows wildlife protection control measures are absent on the stock tank located within the well area.

Inspection Photos
Location Name: Circle B Land Tract 5 /21-692
Facility #: 420296



Photo 3. Photo taken from the southeastern production area adjacent to the tank battery facing north shows weed debris accumulating around equipment in the production area.



Photo 4. Photo taken from the northern entrance to the location facing north shows weed debris accumulating along fences in the interim areas.

Inspection Photos
Location Name: Circle B Land Tract 5 /21-692
Facility #: 420296



Photo 5. Photo taken from the south of the Location facing south shows slopes covered in snow. A follow up inspection is necessary to properly asses stormwater management and interim reclamation.



Inspection Photos
Location Name: Circle B Land Tract 5 /21-692
Facility #: 420296



3/7/22
+39.514645,-107.670423

Photo 6. Photo taken from the east of the Location facing south shows slopes partially covered in snow. A follow up inspection is necessary to properly asses stormwater management and interim reclamation.



3/7/22
+39.514366,-107.670508

Photo 7. Photo taken from the east of the Location facing north. Refer to photo 6 for additional comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800013