

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320029

Mar 10, 2022 at 2:32:31 PM
39.976200,-104.529833
Adams County
COGCC



Pic 1 wellhead, at time of inspection all valves were in the close position. Bradenhead in close position. Small gas leak on packing on wellhead. Unable to tighten hammer union on wellhead.

Mar 10, 2022 at 2:33:09 PM
39.975992,-104.529841
Adams County
COGCC



Pic 2 trash on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320029



Pic 3 gas meter run, separator, storage shed



Pic 4 storage shed, and Separator, trash on location.

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320029

Mar 10, 2022 at 2:34:01 PM
39.975684,-104.529527
Adams County
COGCC




Pic 5 pit

Mar 10, 2022 at 2:34:38 PM
39.975830,-104.529579
Adams County
COGCC



Pic 6 poly tubing on ground

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320029



Pic 7 chemicals stored in storage shed on location.



Pic 8 tank had a spill in past, this spill was never cleaned up from previous inspections. Tank appears to have production fluid stored inside.