

Inspection Photos
Location Name: Abbott 10-43
Location ID: 320523

Mar 10, 2022 at 3:07:50 PM
39.972722,-104.534599
Adams County
COGCC



Pic 1 wellhead, At time of inspection all valves were in close position except one valve that is seized slightly open valves downstream of seized valve are in close position.