

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

07/20/2021

Document Number:

402753813

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

| | |
|--|---|
| OGCC Operator Number: <u>10459</u> | Contact Person: <u>Nathan Bennett</u> |
| Company Name: <u>EXTRACTION OIL & GAS INC</u> | Phone: <u>(570) 932-0776</u> |
| Address: <u>370 17TH STREET SUITE 5200</u> | Fax: <u>()</u> |
| City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> | Email: <u>nbennett@extractionog.com</u> |

Identification Information

| | | |
|--|---------------------------------|--|
| API Number: 05 - <u> </u> - <u> </u> | OGCC Facility ID: <u>456775</u> | Initial Form 19 or 27 Document number: <u> </u> |
| Facility Name: <u>NORTHWEST B PAD</u> | Facility Number: <u> </u> | Facility Type: <u>LOCATION</u> |
| Location QtrQtr: <u>NENW</u> | Section: <u>9</u> | Township: <u>1S</u> |
| | County: <u>BROOMFIELD</u> | Range: <u>68W</u> |
| | | Meridian: <u>6</u> |
| | | Field Name: <u>WATTENBERG</u> |
| Federal, Indian or State Lease Number: <u> </u> | | |

Information Submitted By:

| | | |
|--|--|-------------------------------|
| Company Name: <u>Apex Companies, LLC</u> | Agent Name: <u>Heather Shideman</u> | Title: <u>Project Manager</u> |
| Phone Number: <u>307-620-0117</u> | Email: <u>heather.shideman@apexcos.com</u> | |

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

| | | |
|-------------------------------|------------------------------------|-------------------------------------|
| Facility ID: <u>762158</u> | Facility Name: <u>Henkel 96962</u> | Facility Type: <u>Domestic Well</u> |
| Location: QtrQtr: <u>SWNE</u> | Sec: <u>9</u> | Twp: <u>1S</u> |
| | | Range: <u>68W</u> |
| | | Meridian: <u>6</u> |
| County Name: <u>ADAMS</u> | Latitude: <u>39.979941</u> | Longitude: <u>-105.003942</u> |

Sample Information:

The following Sample Information has been reviewed by the COGCC:

| | | |
|--------------------------------|---------------------------------|--|
| Batch ID: <u>89912</u> | Document Name: <u>Summit</u> | File Name: <u>XOG_BWSE_GWA_Northwest_B_Pad_05-18-2021_Henkel_96962_COGCC.xls</u> |
| Sample Type: <u> </u> | Matrix: <u> </u> | |
| Facility ID: <u>762158</u> | Sample ID: <u>626515</u> | Sample Name: <u>Henkel_96962</u> |
| | | Sample Date: <u>05/18/2021</u> |
| Collection Point: <u>Dom</u> | Matrix: <u>WATER</u> | Pre Post: <u>Voluntary baseline sample</u> |
| Project Number: <u> </u> | Remediation Number: <u> </u> | Complaint Number: <u> </u> |
| | | NOAV Number: <u> </u> |
| Inspection Number: <u> </u> | Spill Number: <u> </u> | Laboratory: <u>Summit Scientific</u> |
| | | Lab Sample ID: <u>2105278-01</u> |

Batch ID: 89913 Document Name: Trip_Blank File Name: XOG_BWSE_GWA_Northwest_B_Pad_05-18-2021_Henkel_96962_Trip_Blank_COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 762158 Sample ID: 626516 Sample Name: Henkel_96962 Sample Date: 05/18/2021

Collection Point: TB Matrix: WATER Pre Post: Trip Blank

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Summit Scientific Lab Sample ID: 2105281-01

Batch ID: 89914 Document Name: SIW File Name: XOG_BWSE_GWA_Northwest_B_Pad_05-18-2021_Henkel_96962_SIW_COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 762158 Sample ID: 626517 Sample Name: Henkel_96962 Sample Date: 05/18/2021

Collection Point: Dom Matrix: WATER Pre Post: Voluntary baseline sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 792769

Batch ID: 89919 Document Name: Energy File Name: XOG_BWSE_GWA_Northwest_B_Pad_05-18-2021_Henkel_96962_Energy_COGCC.xls

SampleType: _____ Matrix: _____

Facility ID: 762158 Sample ID: 626523 Sample Name: Henkel_96962 Sample Date: 05/18/2021

Collection Point: Dom Matrix: WATER Pre Post: Voluntary baseline sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ENERGYLAB Lab Sample ID: G21050427-001A

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

| Sample ID | API Num | Well Name & Num | Sample Reason |
|-----------|-----------|------------------------|---------------------------|
| 626515 | 014-20853 | NORTHWEST B S20-25-19N | Voluntary baseline sample |
| 626515 | 014-20854 | NORTHWEST B S20-25-18N | Voluntary baseline sample |
| 626517 | 014-20853 | NORTHWEST B S20-25-19N | Voluntary baseline sample |
| 626517 | 014-20854 | NORTHWEST B S20-25-18N | Voluntary baseline sample |
| 626523 | 014-20853 | NORTHWEST B S20-25-19N | Voluntary baseline sample |
| 626523 | 014-20854 | NORTHWEST B S20-25-18N | Voluntary baseline sample |

General Comments

| User Group | Comment | Comment Date |
|---------------------|---|--------------|
| Environmental | The data submitted by the operator can be accessed through the COGIS data system. | 03/14/2022 |
| Total: 1 comment(s) | | |