

Inspection Photos

03/09/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334947

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334947



Photo 1: Photo left taken from the access road leading to the Location. Photo right taken from Location entrance. Photos facing North. Photos show control measures / BMPs to stabilize and minimize tracking/sediment transport from the road and Location remains missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334947



March 9, 2022
39.47636831N 108.06104496W



March 9, 2022
39.47636513N 108.06104959W

Photo 2: Photos taken from the Location. Photos examples showing control measures / BMPs to stabilize and minimize tracking/sediment transport from the road and Location remains missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334947



Photo 3: Photos taken from the sediment trap and stormwater outlet on the north end of the Location. Photos show BMP has not been installed in accordance with good engineering practices, or maintained in proper functioning condition.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334947



March 9, 2022
39.4762137N 108.06091342W



March 9, 2022
39.47656797N 108.06099937W

Photo 4: Photos examples showing markers at anchors on Location are missing, or in disrepair.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334947



Photo 5: Photo shows trash debris improperly stored within the secondary containment of the tank battery.