

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6NENW

Location ID: 334628



Photo #6126 from entrance to location.

Photo #6127 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-67S95W /6NENW

Location ID: 334628



Photo #6128 Location lacks stabilization.



Photo #6129 Insufficient tracking control located at the entrance to location.