

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26NWSW

Location ID: 334393



Photo #6166 from entrance to location.



Photo #6167 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /26NWSW

Location ID: 334393



Photo #6168 Location lacks stabilization.



Photo #6169 Insufficient tracking BMP at entrance to location.