

Inspection Photos
Location Name: Anderson 34B
Location ID: 309889



Photo 1: Wellhead Sign



Photo 2: Wellhead



Inspection Photos
Location Name: Anderson 34B
Location ID: 309889




Photo 3: Tank Battery Sign



Photo 4: Centralized Tank Battery



Inspection Photos
Location Name: Anderson 34B
Location ID: 309889



Colorado Oil & Gas Conservation Commission
 40.52739, -104.77135, 1472.4m, 31°
 Mar 15, 2022 1:19:36 PM

Photo 5: Equipment



Colorado Oil & Gas Conservation Commission
 40.52754, -104.77122, 1470.0m, 33°
 Mar 15, 2022 1:18:15 PM

Photo 6: Gas meter not calibrated annually