



Photo #1 Sign at entry to location



Photo #2 netting around pit not continuous.



Photo #3 photos of pit in use. Looking south





Photo #4 Pit netting not continuous. Looking south



Photo #5 looking south





Photo #6 looking southeast.