

Final Reclamation Inspection

March 8, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 310816

Inspection Document #: 697503802

Weld County, CO

SWSE Section 34 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ATREYU F #34-24
Location ID: 310816



Photo 1. Photo taken from the well location, facing West. Photo illustrates all equipment has been removed. Little to no establishment of alfalfa was observed.



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: ATREYU F #34-24
Location ID: 310816



Photo 3. Photo taken from the well location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: ATREYU F #34-24
Location ID: 310816



Photo 5. Reference photo east of the well location, facing East. Photo illustrates alfalfa establishment.



Inspection Photos
Location Name: ATREYU F #34-24
Location ID: 310816



Photo 6. Photo taken from the northwestern portion of the associated offsite tank battery, facing East. Photo illustrates the tank battery has been fenced off. Reference vegetation shown left of the red-dashed line.



Photo 7. Photo taken from the northwestern portion of the associated offsite tank battery, facing South. See comments under Photo 6.



Inspection Photos
Location Name: ATREYU F #34-24
Location ID: 310816



Photo 8. COGCC GISOnline 2017 aerial imagery during active operations with the flowline layer turned on.

