

Inspection Photos
Operator: Simcoe
API: 067-09204
Date: 3/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as crested wheatgrass, intermediate wheatgrass, and sand dropseed.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of open and irrigated grass field and pinyon and juniper woodland (inset) mosaic with understory of sagebrush. Vegetation is largely dormant at this time.