

Inspection Photos  
Operator: Simcoe  
API: 067-09682  
Date: 3/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass, thickspike wheatgrass, and sand dropseed.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of wood debris observed on the well pad, needs to be removed.



Photo 5. View of reference area irrigated grass field with grasses such as thickspike wheatgrass, timothy, and tall fescue.