

Final Reclamation Inspection

March 8, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 329083

Inspection Document #: 697503808

Weld County, CO

SENE Section 34 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: REED #42-34
Location ID: 329083



Photo 1. Photo taken from the associated tank battery, facing North. Photo illustrates the tank battery area is being utilized for cattle operations. It appears heavy use by cattles and the tank battery is a pinch-point for cattle accessing water- see Photo 2. In addition, there is a cattle staging area to the immediate left of the tank battery area- see Photo 3.



Photo 2. Photo taken from the associated tank battery, facing Southeast. See comments under Photo 1.



Inspection Photos
Location Name: REED #42-34
Location ID: 329083



Photo 3. Photo taken from the associated tank battery, facing West. See comments under Photo 1.



Inspection Photos
Location Name: REED #42-34
Location ID: 329083



Photo 4. Reference well photo taken south of the well location, facing West. See comments under Photo 1.



Photo 5. Photo taken from the well location, facing South. See comments under Photo 1.

