

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2022

Submitted Date:

03/16/2022

Document Number:

688000600

FIELD INSPECTION FORM

Loc ID 311873 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|---------------------------------|-----------------------------|-----------------|
| Schneider, Jeff | 970-867-9437/ (214) 244-3819 | jeff@schneiderenergy.com | |
| Bothwell, Kevin | (970) 867-9437 | kbothwell@rivalservices.net | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|---------|-----------------------|-------------|
| 101041 | PIT | AC | | | - | GABAEUER TANK BATTERY | EI |

General Comment:

Environmental inspection. Oil on pit, operator contacted, responding ASAP to remove oil from pit and clean berms.

Inspected Facilities

Facility ID: 101041 Type: PIT API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL _____ Estimated Spill Volume: _____
 Comment: Oil on pit. Wind from the southwest pushing oil across pit to northeast corner.
 Corrective Action: Remove oil from pit and clean pit berms. Date: 03/16/2022
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 688000601 | Location photographs | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5695462 |