

Inspection Photos
Location Name: Thomas Jacquez B #1
API: 05-067-07464



Thomas Jacquez B #1 location photo.

Lube oil containers and produced water PBV with secondary containment.

Inspection Photos
Location Name: Thomas Jacquez B #1
API: 05-067-07464



Compressor within sound walls.



Staining around partially buried 5 gallon bucket.