

# Inspection Photos

API: 043-40014

Operator: JAVERNICK OIL

Inspection Date: 3/15/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/15/2022

## Inspection Photos



**Photo 1.** Drone aerial image facing northeast along the access road. The road has not been recontoured and reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/15/2022

## Inspection Photos



**Photo 2.** Facing northeast along the access road. The road continued to the left (arrow) and the well site was located at right (arrow). Reclamation has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/15/2022

## Inspection Photos



**Photo 3.** Facing northeast toward the location which was never reclaimed. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/15/2022

## Inspection Photos



**Photo 4.** Facing down toward the cut slope of the location which was never recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/15/2022

## Inspection Photos



**Photo 5.** This former access road contuse to a PR well shown at red arrow. The road has not been reclaimed and is no longer in use.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-40014 | Date: 3/15/2022