

Inspection Photos

API: 043-06008

Operator: FOREST OIL CORPORATION

Inspection Date: 3/15/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06008 | Date: 3/15/2022

Inspection Photos



Photo 1. Facing south toward the historic location. A two track road passes thru this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06008 | Date: 3/15/2022

Inspection Photos



Photo 2. Facing south at the historic location. There is a soil mound at the location. No issues were observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06008 | Date: 3/15/2022

Inspection Photos



Photo 3. Facing southwest at the historic location. There is perennial native vegetation established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06008 | Date: 3/15/2022

Inspection Photos



Photo 4. Facing north toward the historic location. There is perennial native vegetation established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06008 | Date: 3/15/2022

Inspection Photos



Photo 5. View of groundcover at the location consists of native vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06008 | Date: 3/15/2022