

TEP
RGU 22-6-298
Location # 316476



location



location

TEP
RGU 22-6-298
Location # 316476



location



Cut slope erosion

TEP
RGU 22-6-298
Location # 316476



Cut slope erosion



Lack of stabilization-compaction

TEP
RGU 22-6-298
Location # 316476



Lack of stabilization-compaction



location

TEP
RGU 22-6-298
Location # 316476



Lack of stabilization-compaction



Access road