



- Photo 1 –



- Photo 2 –



- Photo 3 –



- Photo 4 –



- Photo 5 – Small leak in separator shed



- Photo 6 – Small leak in separator shed visible outside of shed



- Photo 7 –



- Photo 8 – Oil carryover from skim tank accumulated on pit