



Inspection Photos
Collection Station 8,
facility ID 102574
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel

Photo #1



Inspection Photos
Collection Station 8,
facility ID 102574
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel

Photo #2



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Collection Station 8,
facility ID 102574
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel



Photo #3 not all pit netting continuous



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Collection Station 8,
facility ID 102574
Inspection Date: 3/8/2022
All Photos taken by Kris Neidel

Photo #4



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources