

Inspection Photos
Location Name: Crystal-Hubbs 1
Location ID: 320166



Photo 1 WH with TB in background

Photo 2 WH

Inspection Photos
Location Name: Crystal-Hubbs 1
Location ID: 320166




Photo 3 TB sign

Photo 4 TB

Inspection Photos
Location Name: Crystal-Hubbs 1
Location ID: 320166



Photo 5 Vertical Heated Separator and Vertical Sep.

Photo 6 Gas Meter Run

Inspection Photos
Location Name: Crystal-Hubbs 1
Location ID: 320166



Photo 7 Leaking valve on Vertical Heated Separator

Photo 8 Stained soil by leaking valve on Vert. Heated Sep.