

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4: AREA OF IMPACTED SOIL INSIDE COMPRESSOR HOUSE. PHOTO 6: AREA OF IMPACTED SOIL NEAR PRIME MOVER ENGINE SKID. PHOTO 7: AREA OF IMPACTED SOIL NEAR WELLHEAD.		
Corrective Action:	Conduct maintenance on equipment (REPAIR LEAKS), cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D.	Date:	03/16/2022
Type	OTHER		
Comment:	PHOTO 5: APPEARS THAT THE FUEL GAS SEPARATOR IS BEING DRAINED ON THE GROUND.		
Corrective Action:	Conduct maintenance on equipment (DO NOT DRAIN OILY WASTE ON THE GROUND), cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D.	Date:	03/16/2022

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	CATTLE BANEL AROUND WELLHEAD.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 287605 Type: WELL API Number: 071-09041 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/25/2017 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: APPROVED FORM 4 ON FILE DOC #402096220

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: PHOTO 8: OILY WASTE MIXED WITH WATER IN PRIME MOVER ENGINE SKID.
 PHOTO 9: OILY WASTE IN COMPRESSOR SKID CONTAINMENT.

Corrective Action: COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 03/11/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402981446	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5689900
695105804	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5689891