

Inspection Photos

API: 043-06215

Operator: WINN EXPLORATION CO INC

Inspection Date: 3/15/2022



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 3/15/2022

Inspection Photos



Photo 1. Drone aerial photo facing west toward the location. The location was recontoured and reclaimed however a gravel pile was left on the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 3/15/2022

Inspection Photos



Photo 2. Facing west at the location. Perennial vegetation appears to have reestablished throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 3/15/2022

Inspection Photos



Photo 3. The gravel pile remains and should have been removed off the location to complete reclamation of this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 3/15/2022

Inspection Photos



Photo 4. Drone aerial photo facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 3/15/2022

Inspection Photos



Photo 5. There are degraded wattles that remain around the perimeter of the location that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 3/15/2022

Inspection Photos



Photo 6. Southwest side of the location facing north. There are degraded wattles that remain around the location that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06215 | Date: 3/15/2022