

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2022

Submitted Date:

03/17/2022

Document Number:

701600979

FIELD INSPECTION FORM

Loc ID 337949 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 66190
Name of Operator: OMIMEX PETROLEUM INC
Address: 100 CRESCENT COURT, SUITE 700
City: DALLAS State: TX Zip: 75201

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-520-8433	Jeremy_Fisher@omimexgroup.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289934	WELL	PR	02/01/2015	GW	125-10794	BLEDSOE 6-2-5-45	PR

General Comment:

[Routine FIR - SATISFACTORY](#)

Location

Lease Road:

	Type Access		
comment:	Two track grassland		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: NONE

Multiple Spills and Releases?

Fencing/:

	Type PUMP JACK		
Comment:	Steel panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Other	# 0		
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration cert. in place		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	PW transported via pipeline to Mailander SWD 16B-34-6-45				
Corrective Action:				Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)			

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 289934 Type: WELL API Number: 125-10794 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT