

# Final Reclamation Inspection

March 14, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328258

Inspection Document #: 697503816

Weld County, CO

NWSE Section 12 T3N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: OPATRIL #12-10L  
Location ID: 328258



**Photo 1.** Photo taken along the well location access road, facing South. Photo illustrates there is some desirable vegetation but will remain in process. There appears to be drill seeding rows which may have been seeding in the fall of 2021.



Inspection Photos  
Location Name: OPATRIL #12-10L  
Location ID: 328258



**Photo 2.** Photo taken along the well location access road, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: OPATRIL #12-10L  
Location ID: 328258



**Photo 3.** Photo taken from the well location, facing North. Again, the establishment of desirable vegetation is observed and drill seeding rows is evident.

Inspection Photos  
Location Name: OPATRIL #12-10L  
Location ID: 328258



**Photo 4.** Photo taken from the well location, facing Northeast. See comments under Photo 3.





**Photo 5.** 1984 aerial imagery illustrates the well location access road was pre-existing prior to oil and gas.

