

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNW

Location ID: 324175



Photo #6170 from entrance to location.



Photo #6171 Bird protectors missing on separator burners.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNW

Location ID: 324175



Photo #5091 from inspection #699803722.



Photo #6172 Load line open ended.