

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Tri State Trucking /PA 22-25

Location ID: 335123



Photo #6206 from entrance to location.



Photo #6207 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Tri State Trucking /PA 22-25

Location ID: 335123



**Photo #6208** Stored equipment and supplies.

**Photo #6214** Stored equipment and supplies.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Tri State Trucking /PA 22-25

Location ID: 335123



**Photo #6219 Multiple places with trash on location.**



**Photo #6215 Multiple places with trash on location.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Tri State Trucking /PA 22-25

Location ID: 335123



**Photo #6212 Location lacks stabilization.**

**Photo #6213 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Tri State Trucking /PA 22-25

Location ID: 335123



**Photo #6216 Insufficient materials covering and BMP implementation.**