

Rea 18U-03 2 Inspection Doc. # 688801083

Completed CA Photos 02/23/2022.

Removed stained gravel around secondary muffler hose and exhaust. Removed grease from beam unit around the base of pad.

