

Inspection Photos  
Operator: Simcoe  
API: 067-08745  
Date: 3/15/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with grasses such as western wheatgrass and crested wheatgrass, as well as shrubby rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with an understory of black sage, James galleta, penstemon, and snakeweed.