

Inspection Photos
Operator: Simcoe
API: 067-05076
Date: 3/15/2022



Photo 1. View of the southern project area from the southern entrance facing center.



Photo 2. View of the northern project area from the northern well pad entrance facing center.



Photo 3. View of the central fill slope with grasses and shrubs such as sand dropseed, Indian ricegrass, and rubber rabbitbrush.



Photo 4. View of the southwestern project area from the southwestern corner facing northward. Revegetation is progressing in portions of the fill slope, and remains sparse in portions.



Photo 5. View of reference area comprised of pinyon and juniper woodland with an understory of black sage, James galleta, penstemon, and snakeweed.