

Inspection Photos
Operator: Simcoe
API: 067-07868
Date: 3/15/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing here with sand dropseed, western wheatgrass, and Indian ricegrass.



Photo 3. View of revegetation area in the southeastern project area.



Photo 4. View of dense Russian thistles approx 3ft high and 4-6ft wide observed on the well pad.



Photo 5. View of reference area comprised of open sagebrush and grassland with western wheatgrass and James galleta observed.